

Sl. No. 50

GIRLS

SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING BY KANIHA AREA, TALCHER COALFIELDS, MCL

District: - Rayagada

Block: - GUNUPUR

Village: - GUNDURUGAM

School Name: - GUNDURUBA P.S

School Code: -

No. of Student: - 91

Girls: - 69

Boys: - 22

Status of toilet: -

Existing: - ① Boys toilet
② Fully damaged toilet

Not existing: -

Toilet Requirement: -

Girls: -

Boys: -

If Existing: -

Sl no.	Item	Condition	
		① Boys Toilet size - 4.16 X 1.85 X 2.10 Good in Nos.	② Toilet To be replaced in Nos.
1	WC	Good	
2	Urinals	Good	
3	Doors(Size)	GF sheet door - Good 3 NO - 0.70 X 1.85	Fully damaged.
4	Floor level	Tiles - Good.	
5	Wall level	Brick work - Good	
6	Internal Plaster	Good.	
7	Outer plaster	Good	
8	Inspection Chamber	N.A.	
9	Lease Pit/Septic tank	Good.	

Source of Water

Bore well with pump NA /

Hand pump 1 NO

Water tank

Ground NA /

Overhead NA.

Water tank Capacity

Remarks if any:

① Boys toilet is Good condition ^{which is} and presently used as of another toilet is fully damaged.

Sign of School Headmaster

Smt. Mitu Balaraito
Primary School, Gunduruba
Gunupur Block Dt Rayagada

Sign of School Mgt Committee

MATTIU RAITO
S.M.C. P.S. Gunduruba
Dist. Rayagada

Sign of Surveyor

Name Smt. Mitu Balaraito

Name Mattiu Raito

Name Subash Ch Nanda

Email ID

Email ID

Email ID Subash.nanda@gmail.com

Ph.No. 9439087911

Ph.No. 9439249369

Ph.No. 9438878008