

St. No. 66


GIRLS

**SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING
BY KANIHA AREA, TALCHER COALFIELDS, MCL**


District: - Rayagada Block: - **GUNUPUR** Village: - **LADDE**
 School Name: - **LADDE P. S** School Code: - **21270409001**
 No. of Student: - **63** Girls: - **31** Boys: - **32**
 Status of toilet: - Existing: - **Toilet one No.** Not existing: -
 Toilet Requirement: - Girls: - Boys: -
 If Existing: -

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
		Toilet - 4.00 x 1.87 x 1.97	
1	WC	Good - 1 No.	
2	Urinals	Good but NO Urinal pan	
3	Doors(Size)	G.I sheet door with good condition - 2 No. 7.5 x 1.83	
4	Floor level	Tiles - Good	
5	Wall level	B.W with a.m. - Good	
6	Internal Plaster	Good	
7	Outer plaster	Good.	
8	Inspection Chamber	NA.	
9	Lease Pit/Septic tank	Good - 1 No.	

Source of Water Bore well with pump **NA - /** Hand pump **1 no (damaged)**
 Water tank Ground **NA - /** Overhead **NA -**
 Water tank Capacity
 Remarks if any:


 Sign of School Head Master
U.P. SCHOOL, LADDE
 Dist-Rayagada

Dayam Dalbheera
 Sign of School Mgt Committee
S.M.C. U.P. SCHOOL
 Ladde, Dist-Rayagada


 Sign of Surveyor
SOE(C), KA

Name **Debenal n. Pr. Saha**
 Email ID
 Ph.No. **9439649288**

Name **Dayam Dalbheera**
 Email ID
 Ph.No. **7853927078**

Name **Subash Ch Nanda**
 Email ID **Subashnanda@gmail.com**
 Ph.No. **9438878808**