

SL-AG7

GIRLS

**SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING BY KANIHA AREA, TALCHER COALFIELDS, MCL**

District: - Rayagada

Block: - GUNUPUR

Village:- MANENGULU

School Name: - MANENGULU P.S

School Code:- 21270409101

No. of Student: - 30

Girls: - 16

Boys:- 14

Status of toilet: -

Existing: - old toilet on site

Not existing:-

Toilet Requirement: -

Girls: -

Boys:-

If Existing:-

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
		Toilet - size - 4.50x1.40x1.90 (Avg)	
1	WC		Bad condition
2	Urinals		Poor condition
3	Doors(Size)		G.I sheet door 2 Nos but bad condition
4	Floor level		Glazed tiles but bad condition
5	Wall level		Brick work - Good
6	Internal Plaster		Bad condition
7	Outer plaster		Bad condition
8	Inspection Chamber		NA
9	Lease Pit/Septic tank		NA

Source of Water

Bore well with pump NA /

Hand pump / NO

Water tank

Ground NA - /

Overhead NA

Water tank Capacity

Remarks if any: The toilet building is very poor condition.

Signature  
**HEADMASTER**  
 Sign of School Head Master  
 Primary School, Manengul  
 Jaitar Circle, Dist-Rayagada

Signature  
**CHAIRPERSON**  
 Sign of Committee  
 S.M.C. Primary School  
 Manengul, Dist-Rayagada

Signature  
**S. Nanda**  
 Sign of Surveyor

Name Jaipon Gomange

Name

Name Subash & Nanda

Email ID

Email ID

Email ID Subashnanda@gmail.com

Ph.No. 8280983667

Ph.No.

Ph.No. 9438878008