

GIRLS

69

**SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING
BY KANIHA AREA, TALCHER COALFIELDS, MCL**

District: - Rayagada

Block: - GUNUPUR

Village:- MORAMA

School Name:- MULMANGUDA P.S.

School Code:- 21270408502

No. of Student:- 25

Girls:- 12 nos

Boys:- 13 nos

Status of toilet:-

Existing:- ✓

Not existing:-

Toilet Requirement:-

Girls:-

Boys:-

If Existing:-

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	01 (O.K)	
2	Urinals	03 nos (O.K)	
3	Doors(Size)	3 x 0.73 x 1.50 (S/4)	
4	Floor level	O.K	
5	Wall level	O.K	
6	Internal Plaster	O.K	
7	Outer plaster	O.K	
8	Inspection Chamber	N.P.	
9	Lease Pit/Septic tank	O.K	

Source of Water

Bore well with pump NO /

Hand pump 01

Water tank

Ground NO /

Overhead NO

Water tank Capacity

Remarks if any: Every thing is O.K.

Signature of HEADMASTER

for
Primary School, Mulumanguda
Gunupur-Block, Dist. Rayagada.

Name Pradeep Kundo

Email ID

Ph.No. 9178344109

Signature of Chairperson

School Management Committee
Primary School, Mulumanguda
Gunupur Block, Dist. Rayagada

Name Kondekoni Basu.

Email ID

Ph.No.

Signature of Surveyor

Name MANGULU SARA NAYAK

Email ID

Ph.No. 9930773244