

GIRLS 74
SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING
BY KANIHA AREA, TALCHER COALFIELDS, MCL

District: - Rayagada Block: - GUNUPUR Village: - PAGADA BILLA
 School Name: - PAGADA BILLA PROSEC U.P. School Code: - 2127041102
 No. of Student: - 80 Girls: - 42 Boys: - 38
 Status of toilet: - Existing: - Not existing: -
 Toilet Requirement: - Girls: - Boys: -
 If Existing: - Under construction


| Sl no. | Item | Condition | |
|--------|-----------------------|-------------------|------------------------|
| | | Good in Nos. | To be replaced in Nos. |
| 1 | WC | NO | |
| 2 | Urinals | NO | |
| 3 | Doors(Size) | NO | |
| 4 | Floor level | NO | |
| 5 | Wall level | B/w - Under Const | |
| 6 | Internal Plaster | NO | |
| 7 | Outer plaster | Partly done | |
| 8 | Inspection Chamber | NO | |
| 9 | Lease Pit/Septic tank | NO | |

Source of Water Bore well with pump NO / Hand pump 1 (one)
 Water tank NO Ground NO / Overhead NO
 Water tank Capacity NA

Remarks if any: Girls Toilet under construction. B/w done
hand slab done & no fittings & no finishing.

G.M. Vijaya
 Sign of School Head Master
 S.M.C. P.U.P. School, Pagadabilla
 Block-Gunupur Dt-Rayagada

Niranjan Nayak
 Sign of School Mgt Committee
 Head Master
 P.U.P. School, Pagadabilla
 Dist-Rayagada (Orissa)

Sign of Surveyor

 Manguli Jaha Nayak

Name G.M. Vijaya

Name Niranjan Nayak

Name MANGULI JAHA NAYAK

Email ID

Email ID

Email ID

Ph.No. 8280425140

Ph.No. 9438232487

Ph.No. 943873244

BOYS

SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING BY KANIHA AREA, TALCHER COALFIELDS, MCL

District: - Rayagada Block: - GUNUPUR Village:- PAGADA BILLI
 School Name: - PAGADA BILLI PROJECT U.P.S School Code:- 33270411102
 No. of Student: - 30 Girls: - 12 Boys:- 38
 Status of toilet: - Existing: - Not existing:- ✓
 Toilet Requirement: - Girls: - Boys:- 01
 If Existing:- extensive construction is

| Sl no. | Item | Condition | |
|--------|-----------------------|---------------------------------------|------------------------|
| | | Good in Nos. | To be replaced in Nos. |
| 1 | WC | NO | |
| 2 | Urinals | NO | |
| 3 | Doors(Size) | NO | |
| 4 | Floor level | NO | |
| 5 | Wall level | Block chamber NO No. construction. | |
| 6 | Internal Plaster | NO NO | |
| 7 | Outer plaster | No. work. NO | |
| 8 | Inspection Chamber | NO | |
| 9 | Lease Pit/Septic tank | NO | |

Source of Water NO Bore well with pump NO / Hand pump 1
 Water tank Ground NO / Overhead NO
 Water tank Capacity NO

Remarks if any: NO Toilet exists for Boys.

G. M. Vijaya
 Sign of School Head Master
 S.M.C. P.U.P. School, Pagadabilli
 Block-Gunupur Dt-Rayagada

Name G. M. Vijaya
 Email ID
 Ph.No. 8280425140

Sign of School P.T. Committee
 Project U.P. School, Pagadabilli
 Dist-Rayagada (Orissa)

Name Niranjan Nayak
 Email ID
 Ph.No. 9428232489

Sign of Surveyor
 MANGULU SAHA NAYAK

Email ID
 Ph.No. 9932732499