

School Name Babeguda Primary School

School Code 21260205101

No. of Student 106 Girls- 49

Boys- 57

Status of toilet Existing 1 combined

Not Existing

Toilet Requirement Girls

Boys 0 Boys

If Existing:

Sl.No	Item	Condition			
		B	Good in Nos.	G	To be replaced in Nos. G
1	WC		1		0
2	Urinals		1	1	0
3	Doors (size)		3/1	-	-
4	Floor level		-	-	-
5	Wall level		-	-	-
6	Internal plaster		-	-	-
7	Outer plaster		-	-	-
8	Inspection Chamber		-	-	-
9	Lease pit / septic tank		-	-	-

Source of Water

Bore well with pump

Hand pump

Water tank well

Ground

Overhead

Water tank Capacity well

Remarks if any: there is one toilet which is combined build by boys & girls.

there is another toilet is under construction. which requires internal plaster
other plaster, work, door, etc.

[Signature]
 Sign of School head master

[Signature]
 Sign of School Mgt Committee

[Signature]
 Sign of Babeguda
Durga Prasad Kumar

Headmaster
Babeguda P.S.
Golemunda, Kld.
 Name Narasimha Pradhan

Name [Signature]
 Name [Signature]
 (Ward member)

Sourabh Kumar

7894 772695