

Name - / head master -

Mobil No -



District Kalahandi Block Bagmunda

Village Bagmunda

School Name Bagmunda P.S.

School Code 21260309001

No. of Student 72

Girls 32

Boys 41

No. of toilet

Existing NIL (1-girl / 1-ph. under S.N.) Not Existing

Toilet Requirement

Girls ~~32~~ α Boys 01

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		
2	Urinals		
3	Doors (size)		
4	Floor level		
5	Wall level		
6	Internal plaster		
7	Outer plaster		
8	Inspection Chamber		
9	Lease pit / septic tank		

Source of Water Bore well with pump / Hand pump α

Water tank Ground / Overhead

Water tank Capacity

Remarks if any: There is no toilet in the school. So above proposed no. of toilets is urgently required.

Signature of School head master
Headmaster
 Bagmunda Pry. School
 Dist. Kalahandi
 Name Jagsuvarn Majhi
 Ph. 9178151502

Signature of School Mat Committee
Chairperson
 Bagmunda Pry. School
 Bagmunda, Dist. Kalahandi
 Name Maniram Majhi
 Ph. -

Signature of Surveyor
 Name ANIMESH MALDAR
 PHIL KUMAR SATHI