

District Kalabandi Block Golamunda Village BALI PADAR  
 School Name BALI PADAR P.S. School Code 21260307401

No. of Student 42 Girls- 27 Boys- 15

Status of toilet Existing Nil Not Existing 01 latrine (Completely damaged)  
 Toilet Requirement Girls 01 Boys 01 02 Urinals

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		
2	Urinals		
3	Doors (size)		
4	Floor level		
5	Wall level		
6	Internal plaster		
7	Outer plaster		
8	Inspection Chamber		
9	Lease pit / septic tank		

Source of Water Bore well with pump / Hand pump Hand pump

Water tank Ground Ground / Overhead Overhead

Water tank Capacity

Remarks if any: The proposed set of toilets can be constructed only when the existing damaged toilets are demolished, over the same site, as there is shortage of land.

Madan Mohan Majhi Sign of School head master  
BRUNDRAN SAHU Sign of School Mgt Committee  
Amimesh Haldar Sign of Surveyor  
 Headmaster Govt. Primary School Kalabandi  
 Name MADAN MAJHI Name BRUNDRAN SAHU Name AMIMESH HALDAR

9668146701