

Name of head master -

(29)

Mobil NO -

District Kalahandi Block Golamunda Village Dhamanpur
 School Name Borguma P.S. School Code 21260303501
 No. of Student 119 Girls- 55 Boys- 64
 Status of toilet Existing Latrines - 02 Not Existing
Urinals - 02
 Toilet Requirement Girls X Boys 01
 if Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	✓	/
2	Urinals	✓	
3	Doors (size)	—	
4	Floor level	<u>Water</u>	
5	Wall level	✓	
6	Internal plaster	<u>CP</u>	
7	Outer plaster	<u>CP</u>	
8	Inspection Chamber	<u>X</u>	
9	Lease pit / septic tank	✓	

Source of Water Bore well with pump X Hand pump ✓ - 02
 Water tank X Ground X / Overhead X
 Water tank Capacity

Remarks if any: Latrines and Urinals for boys are not available.
Existing latrine is commonly used by boys and girls.

Sign of School Head master
HEADMASTER
 Borguma Centre P.S. School
 Dist. Kalahandi
 Name GURBAN MASHI
 Mob. 9937439181

KURUKSHETRA MASHI
 Sign of School Mgt Committee
Chairperson
 SMC, Centr P.S. School
 Borguma Golamunda V.P.
 Name KURUKSHETRA MASHI
 Mob. 9777242427

Sign of Surveyor
 Name ANIL KUMAR
ANIL KUMAR