

District Khamarunde Block Chakravarti  
 School Name Brunadabahal Center primary school  
 No. of Student 153 Girls 71  
 Status of toilet Existing 1 combined  
 Toilet Requirement Girls ~~1~~ Boys 1 Boys

Village Brunadabahal  
 School Code 21260301407  
 Boys 82  
 Not Existing -  
 Boys 1 Boys

If Existing:

Sl.No	Item	Condition		
		Qty	Good In Nos	Qty To be replaced in Nos
1	WC	1		-
2	Urinals	2		-
3	Doors (size)	5' x 4'		-
4	Floor level	tile		-
5	Wall level	-		-
6	Internal plaster	Yes		-
7	Outer plaster	Yes		-
8	Inspection Chamber	-		-
9	Lease pit / septic tank	Yes		-

Source of Water :  Bore well with pump /  Hand pump  
 Water tank :  on Ground /  Overhead  
 Water tank Capacity : nil

Remarks if any: Existing toilet is using both <sup>to</sup> boys & girls combinedly. Required one toilet for ~~girls~~ Boys.

Sign of School head master

Naik  
 HEADMASTER  
 Brunadabahal C.P.S

Mob no - 91784119500  
 Abhimanyu Naik.

Sign of School Mgt Committee

Eshwari Sankar Rao  
 CHAIR PERSON  
 Name Brunadabahal C.P.S  
 Mob. 08012926566  
 Name - Eshwari Sankar Rao

D. Suresh Kumar  
 19/01/15  
 D. Suresh Kumar  
 Name Suresh Kumar.