

A/head master -

Mobil NO -

District Kalahandi Block Gobamunda Village Karli
 School Name KARLI primary school School Code 21260311101
 No. of Student 38 Girls- 18 Boys- 20
 Status of toilet Existing Latrine Urinal Not Existing
 Toilet Requirement Existing Boys 01 Girls 01 Urinal 01 Boys —
 If Existing: X

Sl.No	Item	Condition			
		B	Good in Nos.	G	To be replaced in Nos. G
1	WC	—	—	01	01
2	Urinals	—	—	01	01 (To be repaired)
3	Doors (size)	0.7 x 1.6 (01 No) 0.7 x 1.8 (01 No)	0.7 x 1.6 (01 No) 0.7 x 1.8 (01 No)	—	—
4	Floor level	—	—	Piles	Piles (To be repaired)
5	Wall level	—	—		
6	Internal plaster				To be repaired
7	Outer plaster	✓	✓		*
8	Inspection Chamber	—	—		✓
9	Lease pit / septic tank	✓	✓		✓

Source of Water Bore well with pump / Hand pump ✓
 Water tank ∅ Ground ✓ / Overhead ∅
 Water tank Capacity ∅

Remarks if any: The existing one needs repair/renovation.

Sign of School head master Mireti Padon
 Sign of School Mgt Committee शिव शंकर शर्मा
 Sign of Surveyor ANIMESH HALDAR

Name BHADANI SHANKAR SENAPATI Name ANIMESH HALDAR
98668285776 ANIL KUMAR SATHI