

Name - / headmaster -

57

Mobil NO -

District *Kalahandi*

Block *Cotampur*

Village *KENDUMUNDI*

School Name *KENDUMUNDI P.S.*

School Code *21260307801*

No. of Student *126* Girls- *57*

Boys- *69*

Status of toilet

Existing *Girls - 01*  
*PH - 01*  
*(Under construction)*

Not Existing

Toilet Requirement

Girls *01*

Boys *01*

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		
2	Urinals		
3	Doors (size)		
4	Floor level		
5	Wall level		
6	Internal plaster		
7	Outer plaster		
8	Inspection Chamber		
9	Lease pit / septic tank		

Source of Water

Bore well with pump /

Hand pump - *01*

Water tank *✓*

Ground *✓*

Overhead *✓*

Water tank Capacity *✓*

Remarks if any: *The toilets under construction is under SSA. There is sufficient land/space for proposed toilets.*

*Markand Jani*  
Headmaster  
Govt. P.S. Kendumundi

*Madhu Maya Sahu*  
Sign of School Mat Committee  
Chairperson  
Govt. P.S. Kendumundi

*Anil Kumar Sahu*  
Sign of Surveyor

Name

Name

Name

*MARKAND JANI*

*MADHUMAYA SAHU*

*ANIL KUMAR SAHU*  
*ANIMESH MALDAR*

*MOB: 9178000560*

*MOB: 8018549766*