

Name - A/Head master -

50

Mobil NO -



District Kalahandi Block Goramunda

Village MAKARAGUDA

School Name MAKARAGUDA P.S.

School Code 21260308702

No. of student 167

Girls- 78

Boys- 89

Status of toilet

Existing Girls - 01 (Under Construction) Not Existing Loo - 02 (Completely damaged)

Toilet Requirement

Girls 01

Boys 01

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		
2	Urinals		
3	Doors (size)		
4	Floor level		
5	Wall level		
6	Internal plaster		
7	Outer plaster		
8	Inspection Chamber		
9	Lease pit / septic tank		

Source of Water

Bore well with pump / Hand pump 0

Water tank 0

Ground / Overhead 0

Water tank Capacity 0

Remarks if any:

One toilet under construction is being done under SSA. One proposed set of toilet can be constructed ~~over the~~ ~~only~~ after the existing damaged one is demolished, as there is shortage of land/space.

Manilal Nial
Sign of School Head master

Gobinda Bag
Chairperson
Sign of School Mat Committee
S.M.C., Govt. Pry. School
Makaraguda

Animesh Halder
Sign of Surveyor

Name
MANILAL NIAL

Name
GOBINDA BAG

Name
ANIMESH HALDAR

MB - 8018216180

MB - 09178299062

ANIL KU SAH