


Name: Rajshree Block: Gobindwadi Village: Huagaon  
 School Name: Huagaon (A) P.S. Section: 2-12-603/0.001  
 No. of Student: 19 Girls: 14 Boys: 5  
 Status of toilet: Existing  New   
 Toilet Requirement: Existing  New

Sl. No.	Item	Condition	
		Good in No.	To be replaced in No.
1	WC		
2	Urinals		
3	Doors (wood)		
4	Floor level		
5	Wall level		
6	Internal plaster		
7	Outer plaster		
8	Inspection Chamber		
9	Leach pit / septic tank		

Source of Water:  Bore well with pump /  Hand pump  
 Water tank /  Ground /  Overhead  
 Water tank Capacity: None

Remarks if any: School is facing huge water supply problem. Request one Day's holiday.

Srikanth Khanna  
 Sign of School Head master

  
 Sign of School Mgt Committee

Sarvesh Kumar  
 Name: Durga Prasad

Head of Block  
 Name: ...  
 Address: ...

Prichna Chandra  
 PRESIDENT  
 Name: Hussain "A" P.S.  
 Address: ...

Mob. no - 091780 70747

