

head master -

①

Mobik NO - 8658547881

District Kalahandi

Block Galamunda

Village Padampur

School Name Padampur Primary School

School Code 21260311501

No. of Student 64

Girls- 23

Boys- 23

Status of toilet

Existing

Latrine Urinal	
Boys - 01	01
Girls - 01	01

Not Existing

Toilet Requirement

Girls

Boys 01

If Existing:

Sl.No	Item	Condition			
		B	Good In Nos.	G	B To be replaced in Nos. G
1	WC	X		X	01 01
2	Urinals	X		X	01 01
3	Doors (size)	0.7 X 1.6 (1 No)	0.7 X 1.6 (1 No)	0.7 X 1.8 (02 No)	— —
4	Floor level	—	—		Tiles to be repaired Tiles to be repaired
5	Wall level				
6	Internal plaster	—	—		To be repaired To be repaired
7	Outer plaster	✓		✓	
8	Inspection Chamber	—	—		
9	Lease pit / septic tank	✓		✓	

Source of Water

Bore well with pump /

Hand pump - 1

Water tank

Ground

Overhead

Water tank Capacity

Remarks if any:

The existing toilets can be repaired.

Signature of School head master

Padampur P.S. School
Galamunda Block

134070 masLi
Name

Sign of School Mgt Committee

Signature of Antaram Majhi

Name ANTARAM MAJHI
Mob- 7854878801

Signature of Surveyor

Sign of Surveyor

Name

ANIMESH HALDAR

ANIL KUMAR SAHU