

me. f/ head master -

Mobil NO -

District Kalahandi Block Gopalaramandan Village SARASGUUDA  
 School Name SARASGUUDA P.S. School Code 21260303001  
 No. of Student 95 Girls 053 Boys 42  
 Status of toilet Existing Girls - 01 (Under Construction) Not Existing 0  
 Toilet Requirement Girls  $\checkmark$  Boys - 01 (usable) Boys 01  
 If Existing:

Sl.No	Item	Condition	
		B Good in Nos. <u>9</u>	B To be replaced in Nos. <u>0</u>
1	WC	$\checkmark$	—
2	Urinals	$\checkmark$	—
3	Doors (size)	<u>0.7 x 1.6 (2 nos)</u> <u>0.7 x 1.8 (1 no)</u>	—
4	Floor level	<u>cp</u>	—
5	Wall level	—	—
6	Internal plaster	—	—
7	Outer plaster	—	—
8	Inspection Chamber	—	—
9	Lease pit / septic tank	$\checkmark$	—

Source of Water Bore well with pump /  Hand pump 01  
 Water tank  $\checkmark$  Ground  $\checkmark$  / Overhead  $\checkmark$   
 Water tank Capacity  $\checkmark$

Remarks if any: The toilet is under construction under sst & the existing one needs repair.

[Signature]  
 Sign of School head master  
**HEADMASTER**  
**Primary School**  
**Sarasguda, Kalahandi**

[Signature]  
**CHAIRPERSON**  
**For School Old Committee**  
**Sarasguda**

[Signature]  
 Sign of Surveyor

Name DAMBARU DHAR MANIWARAR  
 Ph 97777 10485

Name DALIMBAR AGARIA  
 Ph.

Name ANIMESH HALDAR  
ANIL Kumar SAHU