

District - Kullu
 Block - Emalamuda
 Village - Sangguda Sangguda
 School Name - Sangguda Primary School
 School Code - 212 60 305 301
 No. of Student - 117
 Girls - 65
 Boys - 52
 Status of toilet - Existing
 Toilet Requirement - Girls
 Boys

If Existing:

S/No	Item	Condition			
		B	Good in Nos	G	To be replaced in Nos
1	WC	1	-	-	0
2	Urinals	-	-	-	0
3	Doors (size)	-	-	-	0
4	Floor level	-	-	-	0
5	Wall level	-	-	-	0
6	Internal plaster	-	-	-	0
7	Outer plaster	-	-	-	0
8	Inspection Chamber	-	-	-	0
9	Lease pit / septic tank	-	-	-	0

Source of Water - Hand pump / Bare well with pump
 Water tank - nil / Ground / Overhead
 Water tank Capacity - nil

Remarks if any: Under construction toilet was halt temporarily. ~~land~~ that can be used for crinals / handicapped children. Required to ~~be~~ ~~use~~ ~~one~~ ~~boys~~ ~~toilet~~. There is no provision for ~~septic~~ ~~pit~~. ~~one~~ Boys toilet.

Sign of School head master

Sign of School Mgt Committee

Signature of Supervisor
 14/2/15
 Durga Prabodh

Name

Name

Name

Santosh Kumar Rawt
 9556268321

Hansula Tandi

Santosh Kumar