



Date: 16/02/15 Mobil No -

23

District Kolar
 Block Golamunda
 Village Udepur 1624 PM
 School Name Udepur P.S
 School Code 21260306501
 No. of Student 21 Girls 12 Boys 9
 Status of toilet Existing Defunct Not Existing
 Toilet Requirement Girls - 01 girl toilet Boys - X
 If Existing:

Sl.No	Item	Condition	
		B Good in Nos.	C To be replaced in Nos.
1	WC		1
2	Urinals	2	X
3	Doors (size)		
4	Floor level		
5	Wall level		
6	Internal plaster		01
7	Outer plaster		
8	Inspection Chamber		
9	Lease pit / septic tank		

Source of Water Bore well with pump / Hand pump ✓
 Water tank Ground / Overhead
 Water tank Capacity

Remarks if any: Required one circle toilet

Sign of School headmaster
Headmaster
 Udepur P.S. School
 Block Golamunda
 Name Rohit Mallik
 8018958417

21060306501
Chairperson
 Sign of SMC P.S. School
 D. Nagaraj
 Name

Sign of Surveyor
 Suresh Kumar
 Name Durga Prasad
 16/2/15