

22
22

DE-12-01-15

District *Jharsuguda* Block *Jharsuguda* Village *Hirna*
 School Name *Kandagad PS* School Code
 No. of Student *31* Girls- *9* Boys- *22*
 Status of toilet Existing *IND* Not Existing *-*
 Toilet Requirement Girls Boys *1*

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	<i>IND</i>	
2	Urinals	<i>IND</i>	
3	Doors (size)	<i>(0.90x2.0) IND</i>	
4	Floor level	<i>IPS</i>	<i>to be repaired</i>
5	Wall level	<i>Not in good cond</i>	<i>to be repaired</i>
6	Internal plaster	<i>- 40 -</i>	
7	Outer plaster	<i>- 1 -</i>	
8	Inspection Chamber	<i>-</i>	
9	Lease pit / septic tank	<i>-</i>	

Source of Water Bore well with pump */* Hand pump
 Water tank Ground *-* / Overhead *-*
 Water tank Capacity

Remarks if any: - *There is no water connection on toilets*
- Water is carried by bucket for using the toilets.

Sign of School head master
 Name *Dashami Kato*
 Headmaster
 Kandagad Primary School
 Jharsuguda

Sign of School Mgt Committee
 Name *Dashami Kato*
 Headmaster
 Kandagad Primary School
 Jharsuguda

Sign of Surveyor
12/1/15
 Name *B.N. Patel, P.N. Nayak*