

22

Dt-21-1-15

District Tharugada Block Tharugada Village \_\_\_\_\_  
 School Name Kheruel PUPS School Code 2102016901  
 No. of Student 134 Girls \_\_\_\_\_ Boys 58  
 Status of toilet Existing 2 blocky Not Existing \_\_\_\_\_  
 Toilet Requirement Girls overblocky Boys overblocky

If Existing:

SLNo	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	<u>1 No</u>	
2	Urinals		<u>2191 to be repaired</u>
3	Doors (size)		<u>0.507100</u>
4	Floor level	<u>Toilet - Partly IPS 2. 4.10</u>	<u>original - IPS floor</u>
5	Wall level	<u>✓</u>	
6	Internal plaster	<u>✓</u>	
7	Outer plaster	<u>✓</u>	
8	Inspection Chamber		<u>to be replaced</u>
9	Lease pit / septic tank		<u>11</u>

Source of Water \_\_\_\_\_ Bore well with pump / Hand pump ✓  
 Water tank nil Ground / Overhead \_\_\_\_\_  
 Water tank Capacity \_\_\_\_\_

Remarks if any: Students use bucket to carry water for toilet.

Alvin  
 Sign of School Mgt Committee  
 District U. P. School  
 Kheruel, Dt. Tharugada  
 Name Vasudev Bhoisa

Subhramoni Pringali  
 Sign of School Mgt Committee  
 Sign of Surveyor  
 Name \_\_\_\_\_

Billu Singh  
 Sign of Surveyor  
 Name M. K. Bhattacharya  
Billu Singh

Billu Singh