

District Hosuruguda Block Hosuruguda Village Koilaga
 School Name Koilaga Primary School School Code 21020105001
 No. of Student 61 Girls 28 Boys 33
 Status of toilet Existing 2 Block Not Existing
 Toilet Requirement Girls Boys

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	-	Completely damaged (1 No)
2	Urinals	Normal with Ur-Pan	
3	Doors (size)	(0.75 x 1.75)	Damaged Condition.
4	Floor level	Not in good condition	
5	Wall level	- do -	
6	Internal plaster	- do -	
7	Outer plaster	- do -	
8	Inspection Chamber	not	
9	Lease pit / septic tank	not	

Source of Water Bore well with pump / Hand pump ✓

Water tank Ground / Overhead -

Water tank Capacity - Both the blocks are not functioning.
 - There is no toilet.
 - There is no space for new construction.

Remarks if any:

Sign of School Head Teacher
Rolle Date: 17.1.15
 Name Sangita Bag

Sign of School Mgt Committee
Nihar Ranjan Patel
 Name Nihar Ranjan Patel

Sign of Surveyor
P. K. Nayale
 Name P. K. Nayale

[Signature]