

8-20

Dt- 21-1-15

District Jharsuguda Block Jharsuguda Village M. Saletikra  
 School Name M. Saletikra P.S. School Code 21020105801  
 No. of Student 21 Girls 11 Boys 10  
 Status of toilet Existing 1 No Not Existing  
 Toilet Requirement Girls Boys

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	<del>1</del> Not considered	1 no
2	Urinals	nil	
3	Doors (size)	(0.75x1.60)	1 no
4	Floor level	not considered	
5	Wall level	- do -	
6	Internal plaster	- do -	
7	Outer plaster	- do -	
8	Inspection Chamber	nil	
9	Lease pit / septic tank	nil	

Source of Water : Bore well with pump /  Hand pump  
 Water tank : Ground - / Overhead -  
 Water tank Capacity : Water yield is not sufficient on hand pump.  
 - Toilet block is not functioning at present.

Remarks if any:

X  
 Sign of School head master  
K. K. K.  
 Headmaster  
 M. Saletikra P.S. School  
 Block/Dist. Jharsuguda

D. Banbharthra Kalo  
 Sign of School Mgt Committee  
 Name

21-1-15  
 Sign of Surveyor  
B. K. G.  
 Name  
S. K. Patel.

Handwritten signature