

District Mangaluru Block Mangaluru Village Santara, PO - Tal mal
 School Name Mangaluru P.S School Code 21020101801
 No. of Student 3 Girls - Boys 3
 Status of toilet Existing 1 block Not Existing
 Toilet Requirement Girls Boys

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	-	1 NO to be replaced
2	Urinals	n7	
3	Doors (size)	0-75x170	
4	Floor level	NOT ENSURED (onk)	
5	Wall level	-do-	
6	Internal plaster	-do-	
7	Outer plaster	-do-	
8	Inspection Chamber	n7	
9	Lease pit / septic tank	n7	

Source of Water Bore well with pump Hand pump
 Water tank Ground Overhead

Water tank Capacity STRENGTH OF STUDENT IS => 3

Remarks if any:
 - There is no pipe connect^{W/S} on the urinals.
 - Water is carried by the bucket for using the same.

[Signature]
 Sign of School Head teacher
 (Santara Mangaluru)
 Primary School

[Signature]
 Sign of School Mgt Committee
 (Santara Mangaluru)
 Primary School

[Signature]
 Sign of Surveyor
 P. K. NAYAK

Name

Name

Name

[Signature]
 08/1/15



21020101801 – MANGLUPADA PS, TALMAL AREA, JHARSUGUDA



21020101801 – MANGLUPADA PS, TALMAL AREA, JHARSUGUDA, Existing Toilet Status as on 15.01.2015



21020101801 – MANGLUPADA PS, TALMAL AREA, JHARSUGUDA, Existing Toilet Status as on 15.01.2015

