

23

De. 20.01.2015

District Tharuguda Block Tharuguda Village Old Talpatia  
 School Name Old Talpatia PS School Code 21020107102  
 No. of Student 23 Girls 7 Boys 16  
 Status of toilet Existing Not in hand condition Not Existing X  
 Toilet Requirement Girls 1 (Combined block) Boys 1  
 IF Existing:

Sl. No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	<u>Nil</u>	<u>2</u>
2	Urinals		<u>2</u>
3	Doors (size)	<u>1 1/2 x 4'</u>	
4	Floor level	<u>1 PS</u>	
5	Wall level	<u>Plc</u>	
6	Internal plaster	<u>✓</u>	
7	Outer plaster	<u>✓</u>	
8	Inspection Chamber	<u>X</u>	
9	Lease pit / septic tank	<u>X</u>	

Source of Water Bore well with pump / Hand pump  
 Water tank Ground / Overhead

Water tank Capacity

No provision for water. Water is collected from hand pump outside school campus.

Remarks if any: Combined block consisting of 2 WC and 2 urinals. The condition is dilapidated. One separate block for boys & Girls required. One classroom is damaged and can be converted into toilets.

Sign of School head master  
 (Signature)

Sign of School Mgt Committee  
Abhaya Sahu

Sign of Surveyor  
 (Signature)

Name Vedit Kumar Patil  
 (Signature)  
 P.S. Tharuguda  
 Dist. Tharuguda

Name Abhaya Sahu  
 (Signature)  
 P.S. Tharuguda  
 Dist. Tharuguda

Name B T Ramteke  
P K Nayak