

11-9

Dt-21-1-15

District Jharsuguda Block Jharsuguda Village Pandarpattar
 School Name Rabanapada Project PS School Code 21020100402
 No. of Student 41 Girls 24 Boys 17
 Status of toilet Existing 1 Not Existing
 Toilet Requirement Girls Boys

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	1	
2	Urinals	1	
3	Doors (size)	0.80x1.95	
4	Floor level	good	
5	Wall level	-do-	
6	Internal plaster	-do-	
7	Outer plaster	-do-	
8	Inspection Chamber	-	
9	Lease pit / septic tank	1	

Source of Water Bore well with pump / Hand pump
 Water tank Ground * / Overhead -
 Water tank Capacity

Remarks if any: Water is covered by the bucket for using the toilets.
The urinals are having no pans.

X Sign of School head master
Hare Priya Singh
 Name
 Block - Jharsuguda

X Sign of School Mgt Committee
Hare Priya Singh
 Name

21-1-15
 Sign of Surveyor S.K. Patra
 Name

21/1/15