



Master - Atcabind Sabar

10

Mobil No - 9937598234

District Kalahandi Block Junagarh

Village DEUNDI

School Name Deundi P.S.

School Code 2126 0510501

No. of Student 194 Girls- 107

Boys- 87

Status of toilet Existing 02

Not Existing

Toilet Requirement Girls

Boys

If Existing: 01

01

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		✓
2	Urinals		replacement
3	Doors (size)		replacement
4	Floor level		✓
5	Wall level	not good	✓
6	Internal plaster	not good	✓
7	Outer plaster	not good	✓
8	Inspection Chamber	11	✓
9	Lease pit / septic tank	11	✓

Source of Water Bore well with pump / Hand pump ✓
 Water tank Ground / Overhead
 Water tank Capacity

Remarks if any: Existing toilet is required to be maintenance & repair.

Atcabind Sabar
 Sign of School head master
Headmaster
Deundi Primary School
 Name Atcabind Sabar

Ranjan Kumar Singh
 Sign of School Mgt Committee
Chairperson S.M.C
Deundi Primary School
Block- Junagarh
 Name Ranjan Kumar Singh

Ahmad
 Sign of Surveyor
IRFAN AHMAD