

Name of head master - Bigga Kumar Chakraborty (40) Mob/No - 9172222507



Area Kalyanpur Block Itanagarh

School Name Terhali Panch PUPS

No. of Student 111

Grds S/O

Boys 61

Wage Terhali Panch

Serial Code 21240502901

Status of toilet

Existing

New Building ☒

Toilet Requirement

Grds - 9-1

Boys 8-1

# Existing

Sl.No	Item	Condition	
		Good in No.	To be replaced in No.
1	W.C.	1	0
2	Urinal	0	0
3	Door (steel)	0	0
4	Floor level	0	0
5	Wall level	0	0
5	Internal plaster	0	0
7	Outer plaster	0	0
8	Inspection Chamber	0	0
9	Leakage pit/ septic tank	0	0

Source of Water

Bore well with pump

Hand pump ☒

Water Tank

Ground

Overhead ☒

Water Tank Capacity

Remarks: Repair requirement is required on one of student as 111.

Signature of Headmaster

Kumari Jai Lal

Sign of School Headmaster

Signature of Headmaster

Signature of Headmaster

Teacher PUPS

Teacher PUPS

Name of Bigga Kumar Chakraborty Name Kumari Jai Lal

Signature of Headmaster