

District *Kandhamal* Block *Khajuripada* Village *Grabasaru*  
 School Name *Grabasaru P. School* School Code *21210600501*  
 No. of Student *9* Girls- *3* Boys- *6*  
 Status of toilet Existing  Not Existing   
 Toilet Requirement Girls Boys

If Existing:

Sl.No	Item	Condition	
		<i>9</i> Good in Nos.	<i>6</i> To be replaced in Nos.
1	WC		<i>01 Both A &amp; B</i>
2	Urinals		<i>01 NIL</i>
3	Doors (size)		<i>Damaged</i>
4	Floor level		<input checked="" type="checkbox"/>
5	Wall level		<input checked="" type="checkbox"/>
6	Internal plaster		<input checked="" type="checkbox"/>
7	Outer plaster		<input checked="" type="checkbox"/>
8	Inspection Chamber		<input checked="" type="checkbox"/>
9	Lease pit / septic tank		<input checked="" type="checkbox"/>

Source of Water Bore well with pump / Hand pump  - *01 not used*  
 Water tank - *NA* Ground / Overhead  
 Water tank Capacity - *NA*

Remarks if any: *- Toilet is not used.*

*Rajendra Kanhar*  
 Sign of School head master

Sign of School Mgt Committee

*Biswajit Barik*  
 Sign of surveyor

Name **RAJENDRA KANHAR**

Name

Name *Biswajit Barik*