

District **Angul** Block **Kaniha** Village **Kaliadama**  
 School Name **Kaliadama AS** School Code **21150504301**  
 No. of Student **343** Girls- **197** Boys- **146**  
 Status of toilet Existing **5 blocks** Not Existing  
 Toilet Requirement Girls **5** Boys **1**  
 If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	6-B 1-CWSN 8-G	
2	Urinals	7-G	
3	Doors (size)	6m x 1.3 (8) 6m x 1 (2)	
4	Floor level	3m	
5	Wall level	1.8 m	
6	Internal plaster	✓	
7	Outer plaster	✓	
8	Inspection Chamber	NIL	
9	Lease pit / septic tank	Not functioning	

Source of Water Bore well with pump- / Hand pump ~~not~~  
 Water tank Ground / Overhead ~~not~~  
 Water tank Capacity 500 ltr

Remarks if any: - School name given in the list is Kaliadama SS (21150504302), but this school is ~~not existing~~ merged with nearby school Kaliadama AS (21150504301). One toilet block is under construction.

Signature: **Subash Ch. Sahu**, Sign of School Mgt Committee  
 Signature: **Padma Lakshmi Sahu**, Sign of School Headmaster  
 Signature: **Rohith. M.R.**, Sign of Surveyor  
 Name: **Subash Ch. Sahu**  
 Name: **Padma Lakshmi Sahu**  
 Name: **Rohith. M.R.**  
 Contact: **7894607135**

*[Handwritten signature]*  
 08/11/15