

BY KANIHA AREA, TALCHER COALFIELDS, MCL

District: - Rayagada Block: - **KASHI PUR** Village: - **DANGESKHAL**  
 School Name: - **DANGESKHAL P.S** School Code: - **21270604401**  
 No. of Student: - **92** Girls: - **46** Boys: - **46**  
 Status of toilet: - Existing: - **① Old toilet one No.** Not existing: -  
 Toilet Requirement: - Girls: - **② Toilet one No. Under construction** Boys: -  
 If Existing: -

Sl no.	Item	Condition	
		① Old toilet (4.68x1.95x2.10) Good in Nos.	② Under construction (5.20x2.43x2.50) To be replaced in Nos.
1	WC	Bad condition	NA.
2	Urinals	NA.	NA.
3	Doors(Size)	NA.	NA.
4	Floor level	I.P.S Floor = Good	NA.
5	Wall level	B-Wall - Good.	B-Wall - Good
6	Internal Plaster	Good	Good
7	Outer plaster	Good.	Good.
8	Inspection Chamber	NA.	NA.
9	Lease Pit/Septic tank	Available but not in good condit.	Good.

Source of Water Bore well with pump **NA. /** Hand pump **1 No.**  
 Water tank Ground **NA. /** Overhead **NA.**

Water tank Capacity **① The old toilet building is running presently.**  
 Remarks if any: **② One toilet building under construction but not yet functional.**

*[Signature]*  
 Sign of School Head Master  
 ଶ୍ରୀମତୀ ହେମନ୍ତା କୁମାର ମହାନ୍ତ  
 କାଶିପୁର, ରାୟଗଡ଼ା

*[Signature]*  
 Sign of School Mgt Committee  
**CHAIRMAN**  
**S.M.C. Dangeskhal P.U.P.S.**  
**Kashipur, Dist-Rayagada**

*[Signature]*  
 Sign of Surveyor **S.E.(C), KA.**

Name **Hemanta Kumar Mohanta**

Name **Surendra Patra**

Name **Subash Ch Nande**

Email ID

Email ID

Email ID **Subashnande@gmail.com**

Ph.No. **8895745515**

Ph.No. **9439080690**

Ph.No. **9438878808**