


District Bolangir. Block Khapaakhol Village Bhasuamunda.  
 School Name Bhasuamunda UPS. School Code 21240701501  
 No. of Student 117 Girls- 67 Boys- 50  
 Status of toilet Existing Not Existing  
 Toilet Requirement Girls Boys 1

If Existing:


Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		
2	Urinals		
3	Doors (size)		
4	Floor level		
5	Wall level		
6	Internal plaster		
7	Outer plaster		
8	Inspection Chamber		
9	Lease pit / septic tank		

Source of Water Bore well with pump / Hand pump   
 Water tank Not Available Ground / Overhead  
 Water tank Capacity X


Remarks if any: 0! Abandoned toilet.  
0! girls toilet under construction under SSA.

  
 Sign of School head master  
 Govt. N. U. P. S., Bhasuamunda


Name Nruparaj Saha  
9938668621

  
 Sign of School Mgt Committee  
 Govt. N. U. P. S., Bhasuamunda

Name J. Barathan  
Nial

  
 Sign of Surveyor  
 M.T. (min)

Name Saurabh Singh

  
8/11/15