

No 114

Boys - ①

SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING BY KANIHA AREA, TALCHER COALFIELDS, MCL

District: - Rayagada

Block: - KOLNARA

Village:- BAMUNIPINDA

School Name: - BAMUNIPINDA P.S

School Code:- 21270701609

No. of Student: - 14

Girls: - 05

Boys:- 09

Status of toilet: -

Existing: - NA

Not existing:- L

Toilet Requirement: -

Girls: -

Boys:-

If Existing:-

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		
2	Urinals		
3	Doors(Size)		
4	Floor level		
5	Wall level		
6	Internal Plaster		
7	Outer plaster		
8	Inspection Chamber		
9	Lease Pit/Septic tank		

NO TOILETS EXISTS

Source of Water

Bore well with pump NA /

Hand pump NA

Water tank

Ground NA /

Overhead NA

Water tank Capacity

Remarks if any:

*[Signature]*

Sign of School Head Master

*[Signature]*

Sign of School Mgt Committee

Chair Person

*[Signature]*

Sign of Surveyor

S.M.C. Pr. School, Bhamunipinda  
Block-Kolnara, Dist-Rayagada

Name *Lamachandra Gonyo*

Email ID

Ph.No. *9439336117*

S.M.C.Pri.School, Bhamunipinda  
Block-Kolnara, Dist-Rayagada

Name *Paendi Kumburika*

Email ID

Ph.No.

Name *Subash Chandra*

Email ID *Subashmunda@gmail.com*

Ph.No. *9438678808*

GIRLS-0

SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING  
BY KANIHA AREA, TALCHER COALFIELDS, MCL

District: - Rayagada

Block: - KOLNARA

Village: - DAMUNIPINDA

School Name: -

School Code: - 21270701601

No. of Student: - 14

Girls: - 05

Boys: - 09

Status of toilet: -

Existing: - NA

Not existing: ✓

Toilet Requirement: -

Girls: -

Boys: -

If Existing:-

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		
2	Urinals		
3	Doors(Size)		
4	Floor level		
5	Wall level		
6	Internal Plaster		
7	Outer plaster		
8	Inspection Chamber		
9	Lease Pit/Septic tank		

NO TOILETS EXISTS

Source of Water

Bore well with pump NA /

Hand pump NA


Water tank

Ground NA /

Overhead NA

Water tank Capacity

Remarks if any:

  
Sign of School Head Master  
S.M.C.Pri.School, Damunipinda  
Block-Kolnara, Tal- Rayagada

  
Sign of School Mgt Committee  
Chair Person  
S.M.C.Pri.School, Damunipinda  
Block-Kolnara, Dist-Rayagada

  
Sign of Surveyor

Name: Ramachandran G

Name: Paundi Kumbanika

Name: Subash Chandra

Email ID:

Email ID

Email ID: subashmunda@gmail.com

Ph.No. 9438878808

Ph.No.

Ph.No. 9438878808