

**SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING
BY KANIHA AREA, TALCHER COALFIELDS, MCL**

District: - Rayagada Block: - KOLNAAA Village: - KANDACHAMPIA
 School Name: - KANDACHAMPIA P.S School Code: - 21270719102
 No. of Student: - 48 Girls: - 26 Boys: - 22
 Status of toilet: - Existing: - Not existing: -
 Toilet Requirement: - Girls: - Boys: -
 If Existing: - SIZE: 3.78 x 1.55 x 1.20

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	N.A	Required - 01
2	Urinals	N.A	Required - Both side
3	Doors(Size)	N.A	Required - 03
4	Floor level	damaged	To be repair
5	Wall level	O.K	Minor maintenance required
6	Internal Plaster	damaged	To be repair - 50%
7	Outer plaster	damaged 50%	- ok -
8	Inspection Chamber	N.A	N.A
9	Lease Pit/Septic tank	01 (damaged)	damaged 01

Source of Water Bore well with pump NO / Hand pump NO
 Water tank Ground NO / Overhead NO
 Water tank Capacity

Remarks if any: The existing toilet required fully repair.

H. Jaimath Rao
 Sign of School Head Master

SADAPOLAK
 Sign of School Mgt Committee
 (Vice Chairman)


 Sign of Surveyor

Name H. Jaimath Rao Name SADAPOLAK

Name HANMULLI SAMA NAYAK

Email ID: Email ID

Email ID

Ph.No. 8895369141

Ph.No.

Ph.No. 9438773244