

SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING BY KANIHA AREA, TALCHER COALFIELDS, MCL

District: - Rayagada Block: - KOLHARA Village:- KELLIGUDA
 School Name: - KELLIGUDA P.S School Code:-
 No. of Student: - 45 Girls: - 25 Boys:- 20
 Status of toilet: - Existing: - Not existing:-
 Toilet Requirement: - Girls: - Boys:-
 If Existing:- Size: 4.13 x 1.73 x 1.20 with built in side urinal

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	01 (O.K)	
2	Urinals	only side floor	
3	Doors(Size)	01 x 0.58 x 1.37 (Inner) 02 x 0.58 x 1.06 (Street)	All doors are broken
4	Floor level	O.K	
5	Wall level	O.K	
6	Internal Plaster	O.K	
7	Outer plaster	O.K	
8	Inspection Chamber	N.K	
9	Lease Pit/Septic tank	01 (very small)	01

Source of Water Bore well with pump / Hand pump

Water tank Ground / Overhead

Water tank Capacity

Remarks if any:

Ajit Kumar Nilagiri
 Sign of School Head Master
 Primary School
 Kelliguda

S. Rajeswari (Member)
 Sign of School S.M.C. Committee
 Chairman S.M.C.
 Primary School
 Kelliguda

[Signature]
 Sign of Surveyor
 09/04/15
 P.S.K

Name AJIT KUMAR NILAGIRI Name SAILADA RAJESWAR I Name HANGULU FARU NASSU

Email ID: ajitnilagiri@gmail.com Email ID Email ID

Ph.No. 9439248775 Ph.No. Ph.No. 9938733277