

GIRLS

133

**SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING  
BY KANIHA AREA, TALCHER COALFIELDS, MCL**

District: - Rayagada                      Block: - KOLHARA                      Village:- KIAMUNDA  
 School Name: - KIAMUNDA P.S                      School Code:- 21210310002  
 No. of Student: - 57                      Girls: - 33                      Boys:- 24  
 Status of toilet: -                      Existing: -                       Not existing:-  
 Toilet Requirement: -                      Girls: -                      Boys:-

If Existing:- The Girls toilet is under construction size 4.70x2.15x2.10 m.

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	N/A	
2	Urinals	N/A	
3	Doors(Size)	N/A	
4	Floor level	N/A	
5	Wall level	OK	
6	Internal Plaster	N/A	
7	Outer plaster	N/A	
8	Inspection Chamber	N/A	
9	Lease Pit/Septic tank	N/A	

Source of Water                      Bore well with pump    NO /                      Hand pump    01

Water tank                      Ground                      NO /                      Overhead    NO

Water tank Capacity

Remarks if any: This toilet is done upto casting of roof slab only

*Udayanath Kharsla*  
 Sign of School Head Master  
**Headmaster**  
**Primary School**  
**KIAMUNDA**

*Rina Heprika*  
 Sign of School Mgt Committee  
**S. M. C. Chairman**  
**Primary School, Kiamunda**

*[Signature]*  
 Sign of Surveyor

Name *Udayanath Kharsla*

Name RINA HEPRIKA

Name HANGULU SAHA NAYAK

Email ID:

Email ID

Email ID

Ph.No. 9438408560

Ph.No.

Ph.No. 743873244

804A

SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING BY KANIHA AREA, TALCHER COALFIELDS, MCL

District: - Rayagada                      Block: - KOLHARA                      Village:- KIAMUNDA  
 School Name: - KIAMUNDA P.S                      School Code:-21270710002  
 No. of Student: - 57                      Girls: - 33                      Boys:- 24  
 Status of toilet: -                      Existing: -                      Not existing:-   
 Toilet Requirement: -                      Girls: -                      Boys:-

If Existing:- Presently As on 11-02-15 there is no boys toilet in the school

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		
2	Urinals		
3	Doors(Size)		
4	Floor level		
5	Wall level		
6	Internal Plaster		
7	Outer plaster		
8	Inspection Chamber		
9	Lease Pit/Septic tank		

Source of Water                      Bore well with pump    NO /                      Hand pump    01  
 Water tank                      Ground                      NO /                      Overhead    NO

Water tank Capacity

Remarks if any:

*Udayanath Kharsla*  
 Sign of School Head Master  
**Headmaster**  
**Primary School**  
**KIAMUNDA**

*Rina Heprika*  
 Sign of School Mgt Committee  
**S. M. C. Chairman**  
**Primary School, Kiamunda**

*[Signature]*  
 Sign of Surveyor

Name *Udayanath Kharsla*

Name RINA HEPRIKA

Name HANGULU SAHA SAHAI

Email ID:

Email ID

Email ID

Ph.No. 9438 402560

Ph.No.

Ph.No. 9438773277