

Sl.No-137

GIRIS

**SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING BY KANIHA AREA, TALCHER COALFIELDS, MCL**

District: - Rayagada

Block: - KOLNARA

Village:- LEPONA

School Name: - LEPONA P.S

School Code:-

No. of Student: - 29

Girls: - 16

Boys:- 13

Status of toilet: -

Existing: - Yes (no.)

Not existing:-

Toilet Requirement: -

Girls: - (Under construction)

Boys:-

If Existing:-

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	NA	
2	Urinals	NA	
3	Doors(Size)	Steel Door 0.75x1.52	
4	Floor level	Tile	
5	Wall level	Brick work	
6	Internal Plaster	Yes	
7	Outer plaster	Yes	
8	Inspection Chamber	NA	
9	Lease Pit/Septic tank	NA	

Source of Water

Bore well with pump NA /

Hand pump 01 no. (damaged)

Water tank

NA

Ground NA / NA

Overhead

Water tank Capacity

Remarks if any:

under construction

Bidyadhar patel

Sign of School Head Master

Pry. School, Lepona

[Signature]

Sign of School Mgt Committee

[Signature]

Sign of Surveyor

Name

Bidyadhar patel

Name

Name Atul Ranjan Pradhan

Email ID

Email ID

Email ID

Ph.No.

9776919031

Ph.No.

Ph.No.

9861754646