

Boys

SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING BY KANIHA AREA, TALCHER COALFIELDS, MCL

138

District: - Rayagada

Block: - KOLNARA

Village: - KANDACHAMPIA

School Name: - LIPESU P.S

School Code: - 21270714101

No. of Student: - 12

Girls: -

Boys: - 4

Status of toilet: -

Existing: - NEW TOILET BUILDING

Not existing: -

Toilet Requirement: -

Girls: - ONE NO.

Boys: -

If Existing: -

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	Good - 1 No	
2	Urinals	No URINAL PART	
3	Doors(Size)	Steel door - 3 Nos Good.	
4	Floor level	Glazed tiles - Good.	
5	Wall level	B wall - Good.	
6	Internal Plaster	Good	
7	Outer plaster	Good	
8	Inspection Chamber	NA.	
9	Lease Pit/Septic tank	Good.	

Source of Water

Bore well with pump NA /

Hand pump 1 NO.

Water tank

Ground NA /

Overhead NA.

Water tank Capacity

Remarks if any:

Nagathkusan Haik  
Head Master  
Primary School, Lipesu

ଶ୍ରୀମତୀ ସୁବର୍ଣ୍ଣା  
Sign of School Mgt Committee  
V.E.C. President  
LIPESU

S Nande  
Sign of Surveyor

Name Nagathkusan Haik

Name

Name Subash Chandra

Email ID 8280

Email ID

Email ID subashnande@gmail.com

Ph.No. 8280 476445

Ph.No.

Ph.No. 9498878808