

NO 142

GRALSD

SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING BY KANIHA AREA, TALCHER COALFIELDS, MCL

District: - Rayagada Block: - KOLNARA Village: - NANGALPAE
 School Name: - NANGALPAE P.S School Code: - 21272700804
 No. of Student: - 26 Girls: - 10 Boys: - 16
 Status of toilet: - Existing: - one new toilet under construction Not existing:-
 Toilet Requirement: - Girls: - Boys:-
 If Existing:-

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
		Toilet Size - 4.50 x 2.10 x 2.20	
1	WC	NA	
2	Urinals	NA	
3	Doors(Size)	Sturdy door - 3 No. NA Good - 0.75 x 1.5	
4	Floor level	NA	
5	Wall level	B.W with c.m - Good	
6	Internal Plaster	Good	
7	Outer plaster	Good	
8	Inspection Chamber	NA	
9	Lease Pit/Septic tank	Good	

Source of Water Bore well with pump NA / Hand pump - 1 No.
 Water tank Ground NA / Overhead NA
 Water tank Capacity

Remarks if any: The toilet is under construction which is not function presently.

Signature of School Master
 Sashi bhushan Chhwal Singh
 Primary school
 Langalpa, Nalanda

Signature of School Mgt Committee
 PRESIDENT
 S. P. C.
 LANGALPAE

Signature of Surveyor
 Subash Nanda
 SOE (C) KA

Name Sashi bhushan Chhwal Singh
 Email ID
 Ph.No. 9692593342

Name Saranti Kadrago
 Email ID
 Ph.No.

Name Subash Ch Nanda
 Email ID subashnanda@gmail.com
 Ph.No. 9438878808