Boys (196)

SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING BY KANIHA AREA, TALCHER COALFIELDS, MCL

District: - Rayagada Block: - KOLNARA Village:- PATRAPUT

School Name: - PATRAPUT U.S School Code:- 21270706501

No. of Student: - 43 Girls: - 20 Boys:- 23

Status of toilet: - Existing: - NOT EXISTING Not existing:-

Toilet Requirement: - Girls: - Boys:-

If Existing:- AS PER RECORD
Presently there is no toilet existing in the school due to in the Place of Both Boys and Girls toilet one Handicap + Girls toilet Constructed.

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		
2	Urinals		
3	Doors(Size)		
4	Floor level		
5	Wall level		
6	Internal Plaster		
7	Outer plaster		
8	Inspection Chamber		
9	Lease Pit/Septic tank		

Source of Water Bore well with pump NO / Hand pump 01 (NEEDS REPAIR)

Water tank Ground 01 x 0.90 x 0.73 x 0.47 / Overhead

Water tank Capacity

Remarks if any: One new Handicap + Girls toilet Constructed. Size- 4.60 x 2.04 x 2.40 mt.

Ananga Gouango
Sign of School Head Master

Headmaster
Primary School ,Patraput

Sign of School Mgt Committee

S.M.C.President
Patraput Primary Sc

Sign of Surveyor

Name Ananga Gouango

Email ID

Ph.No. 94373/2069

Name SHYAM SINGH KANDARI

Email ID

Ph.No. 8018639935

Name HANGULU JARA NAYAK

Email ID

Ph.No. 7328773244

GIRLS

SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING BY KANIHA AREA, TALCHER COALFIELDS, MCL

District: - Rayagada Block: - KOLNARA Village:- PATRAPUT

School Name: - PATRAPUT P S School Code:- 21270706501

No. of Student: - 43 Girls: - 20 Boys:- 23

Status of toilet: - Existing: - NOT EXISTING. Not existing:-

Toilet Requirement: - Girls: - Boys:-

If Existing:- AS PER RECORD Presently there is no toilet exists in the school due to in the Place of both Boys and Girls toilet one Handicap + Girls toilet is Constructed -

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		
2	Urinals		
3	Doors(Size)		
4	Floor level		
5	Wall level		
6	Internal Plaster		
7	Outer plaster		
8	Inspection Chamber		
9	Lease Pit/Septic tank		

Source of Water Bore well with pump NIL / Hand pump 01 no (Needs repair)

Water tank Ground 01 x 0.90 x 6.73 x 0.47 / Overhead NIL

Water tank Capacity

Remarks if any: One New Handicap + Girls toilet Constructed size- 9.00 x 2.09 x 2.90mt

Ananga Gamango
Sign of School Head Master
Headmaster
Primary School ,Patraput

Sign of School Mgt Committee
S.M.C.President
Patraput Primary Sc

Sign of Surveyor

Name Ananga Gamango Name SHYAMSINGH KANDAGARI Name MANGULU JAHA

Email ID Email ID Email ID

Ph.No. 9437312069 Ph.No. 8018639935 Ph.No. 7738773249