

148

**SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING BY KANIHA AREA, TALCHER COALFIELDS, MCL**

District: - Rayagada      Block: - KOLHARA      Village:- PINDA

School Name: - PINDA P.S      School Code:- 21270713101

No. of Student: - 29      Girls: - 11      Boys:- 18

Status of toilet: -      Existing: -      Not existing:- NOT EXISTING

Toilet Requirement: -      Girls:-      Boys:-

If Existing:- Presently there is no toilet in the school.

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		
2	Urinals		
3	Doors(Size)		
4	Floor level		
5	Wall level		
6	Internal Plaster		
7	Outer plaster		
8	Inspection Chamber		
9	Lease Pit/Septic tank		

Source of Water      Bore well with pump NO /      Hand pump NO

Water tank      Ground NO /      Overhead NO

Water tank Capacity

Remarks if any:

*[Signature]*  
 Sign of School Head Master  
**Headmaster**  
 Pinda Primary School

*[Signature]*  
 Sign of School Mgt Committee  
 Chairman  
**S.M.C Pinda P.U.P School**

*[Signature]*  
 Sign of Surveyor  
 Inspector  
 K.A.S.

Name-GOURANG SAHU      Name-RAM CHANDRA MUNIKA      Name HANGULI SAHA MAYER

Email ID      Email ID      Email ID

Ph.No. 9138711000      Ph.No.      Ph.No. 9138713244