

**SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING
BY KANIHA AREA, TALCHER COALFIELDS, MCL**

District: - Rayagada Block: - KOLNARA Village:- RENGALA PADU
 School Name: - RENGALA PADU P.S School Code:- 21270706601
 No. of Student: - 59 Girls: - 334 Boys:- 264
 Status of toilet: - Existing: - ✓ Not existing:-
 Toilet Requirement: - Girls: - Boys:-
 If Existing:- SIZE - 490 x 250 x 225 (TOILET IS UNDER CONSTRUCTION)

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	-	
2	Urinals	-	
3	Doors(Size)	-	
4	Floor level	-	
5	Wall level	o.k	
6	Internal Plaster	o.k	
7	Outer plaster	o.k	
8	Inspection Chamber	-	
9	Lease Pit/Septic tank	-	

Source of Water Bore well with pump / Hand pump
 Water tank Ground / Overhead
 Water tank Capacity

Remarks if any: TOILET IS CONSTRUCTED UP TO CASTING OF ROOF SLAB and inside and outside plaster done

Sign of School Head Master

**Head Master
Primary School
Rengal Padu**

Name *Sristi Thandakur*

Email ID *anand183619@gmail.com*

Ph.No. *9437847984*

Sign of School Committee

**Chairman
S.M.C.
PS.Rengalpadu**

Name *Paraswati Nayak*

Email ID

Ph.No.

Sign of Surveyor

Name *HANGULU SANA NAYAK*

Email ID

Ph.No. *9938773249*