

Sr. No. 160

Boys ①

SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING BY KANIHA AREA, TALCHER COALFIELDS, MCL

District: - Rayagada Block: - KALNARA Village: SARABAGUDA  
 School Name: - SARABAGUDA P.S School Code: - 2127071050  
 No. of Student: - 24 Girls: - Boys: 15  
 Status of toilet: - Existing: ① Toilet under construction Not existing: -  
 Toilet Requirement: - Girls: ② Old damaged toilet Boys: -  
 If Existing: -

| Sl no. | Item                  | ① Toilet under construction Condition ② Old damaged toilet |   |
|--------|-----------------------|--|---|
|        |                       | Size - 4.60 x 2.30 x 2.00<br>Good in Nos.                  | Size - 5.20 x 1.72 x 1.70 (Avg)<br>To be replaced in Nos. |
| 1      | WC                    | NA   |   |
| 2      | Urinals               | NA   |   |
| 3      | Doors(Size)           | NA   |   |
| 4      | Floor level           | NA   |   |
| 5      | Wall level            | Brick with cm - Good                                       |   |
| 6      | Internal Plaster      | NA   |   |
| 7      | Outer plaster         | NA   |   |
| 8      | Inspection Chamber    | NA   |   |
| 9      | Lease Pit/Septic tank | NA   |   |

fully damaged

Source of Water Bore well with pump NA / Hand pump + NO.  
 Water tank Ground NA / Overhead NA

Water tank Capacity  
 Remarks if any: ① The toilet is under construction. Roof slab already done.  
 ② The toilet is fully damaged which require replacement.

Anjali Khande Siwga  
 Sign of School Head Master  
 Primate

Sign of School Mgt Committee  
 SARABAGUDA

Sign of Surveyor  
 S. Nanda  
 SOE (C) KA-

Name Anjali Khande Siwga  
 Email ID  
 Ph.No. 8763553068

Name Smt. Sabitri Khandegar  
 Email ID  
 Ph.No.

Name Subash Ch Nanda  
 Email ID Subashnanda@gmail.com  
 Ph.No. 9438878808