

**SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING  
BY KANIHA AREA, TALCHER COALFIELDS, MCL**

District: - Rayagada                      Block: - KOLHARA                      Village:- SOURAGUDA  
 School Name: - SOURAGUDA N.P.S                      School Code:- 212707 20201  
 No. of Student: - 30                      Girls: - 18                      Boys:- 12  
 Status of toilet: -                      Existing: -                      Not existing:- ~~NOT EXISTING~~  
 Toilet Requirement: -                      Girls: -                      Boys:-  
 If Existing:- As on 11-02-2015 There is no toilet in the school.

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		
2	Urinals		
3	Doors(Size)		
4	Floor level		
5	Wall level		
6	Internal Plaster		
7	Outer plaster		
8	Inspection Chamber		
9	Lease Pit/Septic tank		

Source of Water                      Bore well with pump    NO    /                      Hand pump    NO  
 Water tank                      Ground    NO                      /                      Overhead    NO

Water tank Capacity

Remarks if any:

*Dellip Kumar Patra*  
 Sign of Head Master  
 New Primary School  
 Souraguda

*L. S. of*  
  
 Sign of School Mgt Committee  
 Chairperson  
 P.S. Souraguda

*[Signature]*  
 Sign of Surveyor

Name *Dellip Kumar Patra*  
 Email ID  
 Ph.No. *9438288614*

Name *Dasavana Bidya*  
 Email ID  
 Ph.No.

Name *HANGULU SABA NATRA*  
 Email ID  
 Ph.No. *7738773294*

GIRLS

SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING BY KANIHA AREA, TALCHER COALFIELDS, MCL

District: - Rayagada                      Block: - KOLWARA                      Village:- SOURAGUDA  
 School Name: - SOURAGUDA N.P.S                      School Code:- 23270720201  
 No. of Student: - 30                      Girls: - 18                      Boys:- 12  
 Status of toilet: -                      Existing: -                      Not existing:- **NOT EXISTING**  
 Toilet Requirement: -                      Girls: -                      Boys:-  
 If Existing:- **As on 01.11.2015 there is no toilet in the school.**

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		
2	Urinals		
3	Doors(Size)		
4	Floor level		
5	Wall level		
6	Internal Plaster		
7	Outer plaster		
8	Inspection Chamber		
9	Lease Pit/Septic tank		

Source of Water                      Bore well with pump    **NO**    /                      Hand pump    **NO**  
 Water tank                      Ground                      **NO**    /                      Overhead    **NO**  
 Water tank Capacity

Remarks if any:

**Dileep Kumar Patraik**  
 Sign of School Master  
**New Primary School**  
**Souraguda**

  
 Sign of School Mgt Committee  
**Chairperson**  
**P.S. Souraguda**

  
 Sign of Surveyor

Name **Dileep Kumar Patraik**  
 Email ID  
 Ph.No. **9438288614**

Name **Dasasana Bidika**  
 Email ID  
 Ph.No.

Name **HANGULU JABA MATAK**  
 Email ID  
 Ph.No. **9438773244**