

170

**SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING
BY KANIHA AREA, TALCHER COALFIELDS, MCL**

District: - Rayagada Block: - *Munigula* Village:-
 School Name: - *Badasiringula, NPS* School Code:- *21270842601*
 No. of Student: - *14* Girls: - *11* Boys:- *03*
 Status of toilet: - Existing: - *Yes* Not existing:-
 Toilet Requirement: - Girls: - Boys:-
 If Existing:- *(Under construction)*

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		
2	Urinals		
3	Doors(Size)		
4	Floor level		
5	Wall level		
6	Internal Plaster		
7	Outer plaster		
8	Inspection Chamber		
9	Lease Pit/Septic tank		

Source of Water Bore well with pump / Hand pump *yes*
 Water tank Ground / Overhead

Water tank Capacity

Remarks if any: *School & Toilet both under const.*

Lima
 Sign of School Head Master
*Primary School, B. Siringula
 Dist-Rayagada*

CHAIRPERSON
 Sign of School Mgt Committee
Siringula, Dist-Rayagada

Pradhar
 Sign of Surveyor

Name *Prabir Kumar Lima*

Name *Surendra Nandan* & *Tapas Ranjan Pradhar*

Email ID

Email ID

Email ID

Ph.No. *7381593190*

Ph.No.

Ph.No. *9938631916*