

GIRLS-①

No. 1711

SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING BY KANIHA AREA, TALCHER COALFIELDS, MCL

District: - Rayagada Block: - MONI GUDA. Village: - **BARMAHALO**
 School Name: - **BARMAHALO P.S** School Code: - **21270814701**
 No. of Student: - **35** Girls: - **19** Boys: - **16**
 Status of toilet: - Existing: - **ONE NO TOILET UNDER CONSTRUCTION** Not existing: -
 Toilet Requirement: - Girls: - Boys: -
 If Existing: -


Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
		Size - 7.30 X 1.80 X 2.20	
1	WC	NA	
2	Urinals	NA	
3	Doors(Size)	NA	
4	Floor level	NA	
5	Wall level	Brick Wall - Good	
6	Internal Plaster	NA	
7	Outer plaster	NA	
8	Inspection Chamber	NA	
9	Lease Pit/Septic tank	NA	

Source of Water - Bore well with pump **NA /** Hand pump / **NO**
 Water tank Ground **NA /** Overhead **NA**
 Water tank Capacity

Remarks if any: **ONE NO NEW TOILET IS UNDER CONSTRUCTION. ROOF SLAB EXISTS IN THE BUILDING.**


 Sign of School Head Master
 ୧୧୧୧ ୧୧୧୧
 ୧୧୧୧ ୧୧୧୧


 Sign of School Mgt Committee
Chairperson


 Sign of Surveyor

Name **Rajendra Kumar Sahu**
 Email ID
 Ph.No. **8270372398**
9438008197

Name **Parandhar Majhi**
 Email ID
 Ph.No. **8895057053**

Name **Subesh Panda**
 Email ID **Subesh.panda@gmail.com**
 Ph.No. **9438878808**