

Sl. NO. - 176

9

**SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING  
BY KANIHA AREA, TALCHER COALFIELDS, MCL**

District: - Rayagada                      Block: - MUNIGUDA                      Village:-  
 School Name: - DANGARBORI N.P.S                      School Code:-  
 No. of Student: - 23                      Girls: - 9                      Boys:- 14  
 Status of toilet: - 2                      Existing: - Yes                      Not existing:-  
 Toilet Requirement: -                      Girls: - (Under Construction)                      Boys:-  
 If Existing:-

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	NA	
2	Urinals	NA	
3	Doors(Size)	0.62 x 2.35	
4	Floor level	NA	
5	Wall level	Brick work	
6	Internal Plaster	NA	
7	Outer plaster	NA	
8	Inspection Chamber	NA	
9	Lease Pit/Septic tank	Yes (Under Construction)	

Source of Water                      Bore well with pump    NA /                      Hand pump    01 No  
 Water tank                      NA                      Ground                      NA /                      Overhead    NA  
 Water tank Capacity

Remarks if any: School & Toilet Both under Const<sup>n</sup>

*Bijoya K. Mishra*  
 Sign of School Head Master  
 Headmaster  
 Primary School, Dangarbori  
 Tal - Rayagada

Name *Bijoya K. Mishra*

Email ID *mr.bijoy444@rediffmail.com*

Ph.No. *9124934230*

*[Signature]*  
 Sign of School Mgt Committee  
 Chairperson:    [Signature]  
 Dangarbori Primary School

Name

Email ID

Ph.No.

*[Signature]*  
 Sign of Surveyor

*Tapas Ranjan Prasad*  
 Name

Email ID

Ph.No. *9938631916*