

SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING  
BY KANIHA AREA, TALCHER COALFIELDS, MCL

177

District: - Rayagada

Block: - *muneguda*

Village: - *Dulerigaon*

School Name: - *NPS DULERIGAON*

School Code: - *21270815601*

No. of Student: - *29*

Girls: - *13*

Boys: - *16*

Status of toilet: -

Existing: - *Under construction* Not existing: -

Toilet Requirement: -

Girls: -

Boys: -

If Existing: -

*5.40 x 1.90 x 2.10*

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	<i>N.A</i>	<i>1</i>
2	Urinals	<i>N.A</i>	<i>3</i>
3	Doors(Size)	<i>3 0.60 x 2.10</i>	
4	Floor level	<i>NA</i>	<i>tile</i>
5	Wall level	<i>Boick ms</i>	
6	Internal Plaster	<i>N.A</i>	
7	Outer plaster	<i>N.A</i>	
8	Inspection Chamber	<i>N.A</i>	<i>2</i>
9	Lease Pit/Septic tank	<i>N.A</i>	<i>1</i>

Source of Water

Bore well with pump *NA /*

Hand pump *N.A*

Water tank

Ground *NA /*

Overhead *N.A*

Water tank Capacity *N.A*

Remarks if any:

*Handwritten notes and symbols*

*Alexha Chandru Malley*

Sign of School Head Master

*Handwritten signature*  
 Sign of School Mgt Committee

*Handwritten signature*  
 Sign of Surveyor

Name *Alexha Chandru Malley*

Name *Abhinav Kumar*

Name *Tapas Ranjan Pradhan*

Email ID

Email ID

Email ID

Ph.No. *9437294874*

Ph.No

Ph.No. *9938631916*