

*Girls*  
**SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING  
 BY KANIHA AREA, TALCHER COALFIELDS, MCL**

No (179)

District: - Rayagada                      Block: - **MUNIGUDA**                      Village:- **GOLGOLA**  
 School Name: - **NPS, GOLGOLA**                      School Code:- **21270841501**  
 No. of Student: - **29**                      Girls: - **10**                      Boys:- **19**  
 Status of toilet: -                      Existing: -                      Not existing:-  
 Toilet Requirement: -                      Girls: -                      Boys:-  
 If Existing:-

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		
2	Urinals		
3	Doors(Size)		
4	Floor level		
5	Wall level		
6	Internal Plaster		
7	Outer plaster		
8	Inspection Chamber		
9	Lease Pit/Septic tank		

NO TOILET

Source of Water                      Bore well with pump                      / NA                      Hand pump                      NA

Water tank                      Ground                      NA /                      Overhead                      NA

Water tank Capacity

Remarks if any:

**NO School building & Toilet**

Sign of School Head Master  
 Headmaster

**GOLGOLA N.P. SCHOOL**  
 Block Muniguda Dt. Rayagada

Name **Adinarayan  
 Mandika**

Email ID

Ph.No. **7873901001**  
**9437396003**

Sign of School Mgt Committee  
 Chairperson

**S.M.C. GOLGOLA N.P.S**  
 Block Muniguda, Dt. Rayagada

Name **Nodi Sikka**

Email ID

Ph.No.

Sign of Surveyor

**Jayes Ranjan Pradha**  
 Name

Email ID

Ph.No. **9938631916**