

"Girls"

SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING BY KANIHA AREA, TALCHER COALFIELDS, MCL

No. 184

District: - Rayagada

Block: - MUNIGUDA

Village:- KUDUBARU

School Name: - KUDUBARU NPS

School Code:- 21270841601

No. of Student: - 56

Girls: - 26

Boys:- 30

Status of toilet: -

Existing: - ONE TOILET UNDER CONSTRUCTION.

Not existing:-

Toilet Requirement: -

Girls: -

Boys:-

If Existing:-

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	NA	
2	Urinals	NA	
3	Doors(Size)	NA	
4	Floor level	NA	
5	Wall level	Brick way - Good up to lintel	
6	Internal Plaster	NA	
7	Outer plaster	NA	
8	Inspection Chamber	NA	
9	Lease Pit/Septic tank	NA	

Source of Water

Bore well with pump NA: /

Hand pump NA.

Water tank

Ground NA: /

Overhead NA.

Water tank Capacity

Remarks if any: The toilet is under construction up to lintel level.

Behara
Sign of School Master
Kudubaru N.P.S

Balaram Dongori
Sign of School Mgt Committee
Chairperson S.M.C.
Kudubaru Pry. School

S Nanda
Sign of Surveyor
SOE(C), KA

Name Prafulla K. Behara
906

Name Balaram Dongori

Name Subash Ch Nanda.

Email ID

Email ID

Email ID Subashmunda@gmail.com

Ph.No. 9040235122

Ph.No. 9438043821

Ph.No. 9438878808