

No. 189

GIRLS

SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING BY KANIHA AREA, TALCHER COALFIELDS, MCL

District: - Rayagada

Block: - MUNIGUDA

Village:- NUASAHI

School Name: - NUASAHI N.P.S

School Code:- 21270842701

No. of Student: - 25

Girls: - 09

Boys:- 16

Status of toilet: -

Existing: - NEW TOILET ONE UNDER CONSTRUCTION

Not existing:-

Toilet Requirement: -

Girls: -

Boys:-

If Existing:-

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
		Size - 5.05 X 2.00 X 2.40	
1	WC	NA	
2	Urinals	NA	
3	Doors(Size)	NA	
4	Floor level	NA	
5	Wall level	Brick wall - Good	
6	Internal Plaster	Good	
7	Outer plaster	Good	
8	Inspection Chamber	NA	
9	Lease Pit/Septic tank	NA	

Source of Water

Bore well with pump NA /

Hand pump NA

Water tank

Ground NA /

Overhead NA

Water tank Capacity

Remarks if any: The toilet is under construction. Roof slab is done.

Sign of School Head Master



Member School Mgt Committee

Sign of Surveyor

Head Master  
N. P. S Nuasa

S. M. C. CHAIRPERSON  
N. P. S, Nuasa  
Munguda, Dist-Rayagada

Name: [Signature]

Name: Brumola Kadraua

Name: Subash Ch Wanda

Email ID:

Email ID:

Email ID: subashnanda@gmail.com

Ph.No. 9776745714

Ph.No.:

Ph.No. 9498878008